



Installing the Birdie-FTR on a Windows 8 /10 system.

Copy the “Birdie” subdirectory and its contents to the C:\, the root directory. Then right click on the “Birdie\_v1\_38.exe” select properties.



Now select the “Compatibility” tab.



Select run this program in compatibility mode for: Windows XP service pack 3.

Also select the box that sets “run the program as an administrator.”

Hit ok.

Now right click “Birdie\_v1\_38.exe” create shortcut which you can place on the desktop.

Note the serial port needs to be in the range of COM1 to COM4. USB to serial converters do work but we have had to use the advanced setting on the Device manager for the USB to serial device to force it to come up as COM1 – COM4.